



Release Notes for CradlePoint rev 1.6 Firmware

Products supported/tested:

CradlePoint Travel Router (CTR-350)

Phone modems/handsets tested:

Novatel U720 Modem/Sprint and Verizon

Novatel U727 Modem/Sprint

Sierra Wireless Aircard 595U Modem/Sprint

Motorola v3c RAZR/Sprint and Verizon

LG VX8000/Verizon

LG VX7200/Verizon

Samsung A920/Sprint

Sanyo M1/Sprint

RIM BlackBerry 8703e/Sprint and Verizon (CTR-350 only)

New features added in this release:

- Improvement of web pages, including Safari browser changes
- Added BlackBerry 8703e support to CTR-350

Firmware errata:

- BlackBerry 8703e does not charge correctly on CTR. This will be fixed in the next release.
- The routers default to “Super G(tm)” mode for wireless performance. Multiple routers in close proximity can have conflicts. If you notice wireless LAN disassociation issues, please disable this mode from the Administration pages. Basic -> Wireless -> Super G Mode: Disabled.
- No webpage on reset all settings (Tools->System)
- The Configuration File not checked during “Restore Configuration from File” (Tools -> Admin), and can push bad data causing a JavaScript scripting error.
- WDS is broken and should not be set (Advanced -> Advanced Wireless)
- PHS wizard has option for cable/Ethernet connection (Old issue) that shouldn't appear.