



## Release Notes for Cradlepoint rev 2.0.1 Firmware

### ***Products supported/tested:***

Cradlepoint Travel Router (CTR350)

Personal Hotspot (PHS300)

### ***Phone modems/handsets supported:***

#### **Modems**

Novatel U720 Modem/Sprint and Verizon

Novatel U727 Modem/Sprint

Sierra Wireless Aircard 595U Modem/Sprint and Verizon

Sierra Wireless 881 USB/AT&T

Franklin CDU-680/Sprint

Franklin CDU-550/Sprint

Pantech UM150/Verizon

Option GT Max 3.6 Express/AT&T\*

Note: Requires an ExpressCard-to-USB adapter that provides 1.2V

#### **Handsets**

Motorola v3c RAZR/Sprint and Verizon

Motorola RAZR2/Sprint

Motorola Q (original, not 9c)/Sprint

LG VX8000/Verizon

LG VX7200/Verizon

Samsung A920/Sprint

Samsung i830/Sprint

Sanyo M1/Sprint

Sanyo Katana 2/Sprint

RIM BlackBerry 8703e/Sprint and Verizon (CTR only)

RIM BlackBerry 8830/Sprint

LG Musiq/Sprint

Palm 700w/Sprint

Palm 700p/Verizon

Palm 755p/Sprint

Samsung SGH-A707/AT&T

Samsung Blackjack/AT&T

Motorola RAZR v3xx/AT&T

Motorola Q v9h/AT&T

### ***New features added in this release:***

- None. Defect fix only

### ***Firmware errata:***

- WPA2 and TKIP Issue - Setting the WPA Mode to "WPA2 only" and the Cipher Type to "TKIP" can put the unit into an unrecoverable state. Products Affected are the CTR350 and PHS300.
  - Work Around - Set the WPA Mode to "WPA2 only" and the Cipher Type to "TKIP and AES"

### ***UI/usability changes:***

- Fixed a defect where a configuration restore (Tools -> Admin) from any version including 2.0 would raise an error.

### ***Minor changes:***

- None