



## Release Notes for Cradlepoint MBR rev 1.1.1 Firmware

### ***Products supported/tested:***

Mobile Broadband Router (MBR1000)

### ***Phone supported:***

USB modems:

Novatel U720 Modem/Sprint and Verizon

Novatel U727/Sprint

Franklin CDU-680/Sprint

Sierra Wireless U595/Sprint and Verizon

Sierra Wireless 881U (AT&T USBConnect 881)/AT&T

Franklin CDU-550/Sprint

Pantech UM-150/Verizon

ExpressCard modems:

Novatel V740/Verizon

Kyocera KPC-680/Sprint and Verizon

Sierra Wireless 597E/Sprint

Option GT Max 3.6 Express/AT&T

Handsets:

Sanyo M1/Sprint

Samsung A920/Sprint

Samsung i830/Sprint

LG Muziq/Sprint

LG VX8000/Verizon

Motorola v3c RAZR/Sprint and Verizon

RIM BlackBerry 8703e/Sprint and Verizon

RIM BlackBerry 8830/Sprint

Motorola RAZR2/Sprint

Motorola Q (original, not 9c)/Sprint

Palm 700w/Sprint

Palm 700p/Verizon

Palm 755p/Sprint

Samsung SGH-A707/AT&T

Samsung Blackjack/AT&T

Motorola RAZR v3xx/AT&T

## Motorola Q v9h/AT&T

### **Features:**

- 80211.b/g/n
- Four LAN ports, WAN port
- USB modems/phones
- ExpressCard modems
- Failover
- WiPipe upstream latency measurement on ethernet WAN port
- WDS support

### **New Features added in this release:**

- None. Defect fix only.
- Fixes for modem Failover and Failover UI-related defects.

### **Firmware errata:**

- None