



## **Release Notes for CradlePoint rev 1.7.1 Firmware**

### ***Products supported/tested:***

CradlePoint Travel Router (CTR-350)  
CradlePoint Personal Hot Spot (PHS300)

### ***Phone modems/handsets tested:***

#### **Modems**

Novatel U720 Modem/Sprint and Verizon  
Novatel U727 Modem/Sprint  
Sierra Wireless Aircard 595U Modem/Sprint and Verizon  
Franklin CDU-680/Sprint

#### **Handsets**

Motorola v3c RAZR/Sprint and Verizon  
LG VX8000/Verizon  
LG VX7200/Verizon  
Samsung A920/Sprint  
Samsung i830/Sprint  
Sanyo M1/Sprint  
Sanyo Katana 2/Sprint  
RIM BlackBerry 8703e/Sprint and Verizon (CTR-350 only)  
RIM BlackBerry 8830/Sprint  
LG Muziq/Sprint

### ***New features added in this release:***

- None, defect fix only release

### ***Defects fixed:***

- Fixed associate/disassociate problem seen with Intel wireless clients
- Fixed problem found with Franklin CDU-680 use where the connection would drop and re-

establish repeatedly.

***Firmware errata:***

- The Configuration File is not checked during “Restore Configuration from File” (Tools -> Admin), and can push bad data causing a JavaScript scripting error.